



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-2086/1

Work Order Type: Weatherization

Audit Name: Audit (116)

CLIENT INFORMATION

Client Name: N/A

Address:

Client ID: 17017UC-2086

Alt. Client ID: DEKALB

CLIENT CONTACT INFORMATION

N/A

Applicant/Person of
Record



AGENCY INFORMATION

Agency: Upper Cumberland Human Resource Agency

Agency Phone: (931) 528-1127

Address: 580 South Jefferson Avenue, Suite B
Cookville, TN 38501

Fax: (931) 526-8305

Email Address:

Agency Contact: Smith, Richmond

Work Phone:

Cell Phone:

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

AUDITOR : RICHMOND SMITH

HOME BUILT IN 1930

Measures

Measure 1 DOOR REPLACEMENT X 2				Components			Inspected		
Comment REPLACE DR1 & DR2 W/INSULATED STEEL DOOR UNITS							<input type="checkbox"/>		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Measure 2 LOOSEN WINDOWS X 7				Components			Inspected		
Comment FREE UP TIGHT WINDOWS SO CLIENT CAN OPERATE. A1, B6, C7, D8, D9, D10, & A11.							<input type="checkbox"/>		
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Measure 3 REPLACE STORM WINDOW**Components****Inspected****Comment** REPLACE STORM ON E12. APPROX 56 X 42☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 Infiltration Redctn****Components****Inspected**

Comment GLAZE AND CAULK EXT. WINDOWS A1, C7, D8, D9, A10, A11, & E12.
REPLACE BROKEN SINGLE STRENGTH GLASS X 2 D10 (24 X 16) & A11
(24 X 20). SEAL PLMB PENETRATIONS UNDER KITCHEN & BATH
SINKS.

☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name: N/A

Client ID: 17017UC-2086

Alt. Client ID: DEKALB

Work Order (Bid Form)

Work Order Name: WO/17017UC-2086/1

Report Run On: 4/16/2012

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 8

Measure 5 User-Spec Ceiling R**Components** ATC1**Inspected****Comment** W/STRIP EXISTING ATTIC HATCH & ADD R30 TO LID☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	936	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	936	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Miscellaneous Su	Added Misc Cost - Cellulose, Blown - R-38	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 Window Replacement****Components** A2**Inspected****Comment** REPLACE WINDOWS A2, A3, A4, & A5 W/VINYL INSULATED
REPLACEMENT WINDOWS.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Window Replacement	SqFt	37.33	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Window Replacement	SqFt	37.33	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Other	Window Replacement	Each Window	4	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name: N/A

Client ID: 17017UC-2086

Alt. Client ID: DEKALB

Work Order (Bid Form)

Work Order Name: WO/17017UC-2086/1

Report Run On: 4/16/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 8

Measure 7 DWH Tank Insulation				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 8 Lighting Retrofits				Components L1,L2				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact FI. - 13 Watt	Each Lamp	3					
2	Labor	Compact FI. - 13 Watt	Each Lamp	3					
3	Lighting	Compact FI. - 13 Watt	Each Lamp	3					
4	Labor	Compact FI. - 13 Watt	Each Lamp	3					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 9 DWH Pipe Insulation**Components****Inspected****Comment** WRAP 4 FT HOT & COLD LINES @ W/HTR☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 10 Wall Insulation****Components** E1,E2,N1,S1,S2,W1**Inspected****Comment** DRILL & DENSE PACK ALL EXT WALLS☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	873.6	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	873.6	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name: N/A

Client ID: 17017UC-2086

Alt. Client ID: DEKALB

Work Order (Bid Form)

Work Order Name: WO/17017UC-2086/1

Report Run On: 4/16/2012

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 8

Measure 11 CO Monitor is Needed				Components				Inspected	
Comment									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 12 Fix Improper Venting (Clothes Dryer)				Components				Inspected	
Comment REPLACE DRYER VENT KIT									
				Estimated		Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

**Measure 13 Practice Lead Safe Weatherization
(Walls)****Components****Inspected****Comment** PRACTICE LEAD SAFE PRACTICES ON 2 DOOR REPLACEMENTS & 4
WINDOWS☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Measure 14 Smoke Detector is Needed****Components****Inspected****Comment** INSTALL 2 SMOKE DETECTORS☐

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
				<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:**Work Order Grand Total:****Grand Total:**

Client Name: N/A

Client ID: 17017UC-2086

Alt. Client ID: DEKALB

Work Order (Bid Form)

Work Order Name: WO/17017UC-2086/1

Report Run On: 4/16/2012

DOE Weatherization Assistant

Version 8.6.0

Page 8 of 8